



slimSTAND assembly artwork





To have the goose neck head be past through the holder head. Then put 2 screw washer and fix by M8 screw hat well. Finally, cover the holder neck.





Goose Neck

To pass through the goose neck by the other side to the stand hold. Then put the screw washer and fix by M8 screw well. Finally, cover the metal base and fix by M2.6X8 screw by 4pcs.



(Metal base)



(Completed view)